small size

HEAT INDEX WBGT METER

Model: WBGT-208

ISO-9001, CE, IEC1010



small size HEAT INDEX WBGT METER Model : WBGT-208

FEATURES

*	Introduction :
	WBGT (wet-bulb globe temperature) was developed as a monitoring
	basis at US military training camps and became widespread for
	the use in workplaces and sports situation It is suggested in the
	international standard ISO 7243, OSHA (US Occupation Safety),
	Japan Society for Occupational Health and the SMA (Sports
	Medicine Australia) in establishing the permissible heat
	exposure limits in health , sports or other physical activities.
*	
	globe temperature), Black globe temperature, Humidity,
	Air temperature, Wet bulb temperature, Dew point Temp
*	Adjustable WBGT alarm setting, if the WBGT value over the alarm
	threshold, the buzzer will sound along with the flashing Display.
*	Using to control and monitor of physical activity in hot
	environment to limit the danger of heat related injuries.
*	Globe temperature measurement use the Pt sensor, high accuracy.
*	r ast numuity measuring response time.
*	Direct measurement of the radiation effect with
	a brass black ball in 40 mm dia.
*	
*	LCD with green light backlight, easy reading.
*	Can default auto power off or manual power off.
*	Data field, fecold fliax. and fillin. feading.
*	
*	Fower by OWH/AAA (1.5 V) X 5 ballenes .
*	RS232/USB PC COMPUTER interface.

General Specifications

General Specifica				
Circuit	Custom one-chip of microprocessor LSI circuit.			
Display	LCD size : 52 mm x 38 mm			
	LCD with green backlight (ON/OFF).			
Measurement	 Wet bulb globe temperature (WBGT) 			
	@ Indoor/Outdoor			
	* Black globe temperature (TG)			
	* Air temperature (TA)			
	* Wet bulb temperature (WB)			
	* Humidity			
	* Dew point temperature			
WBGT formula	Indoor/Outdoor and no sun :			
* Wet bulb	WBGT = (0.7 x WB) + (0.3 x TG)			
globe Temp.	Outdoor and full sun :			
	WBGT = (0.7 x WB) + (0.2 x TG) + (0.1 x TA)			
WBGT alarm	Adjustable WBGT alarm setting, if the			
setting	WBGT value over the alarm threshold, the			
0	buzzer will sound along with the flashing Display.			
Advanced	* Set WBGT alarm value			
setting	* Auto power OFF management			
5	* Set beep Sound ON/OFF			
	* Select the temperature unit to °C or °F.			
Data Hold	Freeze the display reading.			
Memory Recall	Maximum & Minimum value.			
Sampling Time	Approx. 1 second.			
of Display				
Data Output	RS 232/USB PC computer interface.			
	* Connect the optional RS232 cable			
	UPCB-02 will get the RS232 plug.			
	* Connect the optional USB cable			
	USB-01 will get the USB plug.			
Operating	0 to 50 °C.			
Temperature				
Operating	Less than 85% R.H.			
Humidity				
Power Supply	* Alkaline or heavy duty DC 1.5 V battery			
. end cappiy	(UM4/AAA) x 3 PCs, or equivalent.			
Power Current	* If LCD Backlight is off, the power			
	consumption will be approx. 5 mA.			
	 If LCD backlight on, the power 			
	in LOD backlight on, the power			
Woight	consumption will be approx. 11 mA.			
Weight	489 g/1.08 LB.			
Dimension	Meter : 177 x 57 x 24 mm (7.0 x 2.2 x 0.94 inch)			
0, , ,	Black brass ball : Round, 40 mm dia			
Standard	* Instruction manual 1 PC			
Accessories	* Black brass ball (with sensor) 1 PC			
Included	* Soft carrying case, CA-05B 1 PC			
Optional	* USB cable, USB-01.			
Accessories	* RS232 cable, UPCB-02.			
	* Data Acquisition software,SW-U801-WIN.			
	* Soft carrying case, CA-52A			

Electrical Specifications (23±5 °C)

Range	°C	Indoor	0 ℃ to 59 ℃	
0		Outdoor	0 ℃ to 56 ℃	
	°F	Indoor	32 to 138 °F	
		Outdoor	32 to 132 °F	
Accuracy	°C	±1 ℃ (15 to 59 ℃)		
* Indoor		±1.5 °C (Others)		
	°F	±1.8 °F(59 to 138 °F)		
		±2.7 °F (0	Others)	
Accuracy °C		±1.5 ℃ (1	15 to 56 ℃)	
* Outdoor		±2 °C (Others)		
	°F	±2.7 °F (5	±2.7 °F (59 to 132 °F)	
		±3.6 °F (0	Others)	

WBGT Formula :

Indoor	WBGT= 0.7WB + 0.3TG
(Outdoor and no sun)	
Outdoor	WBGT= 0.7WB + 0.2TG + 0.1TA
(Outdoor and full sun)	

Air temperature (TA)			
Range	°C	0 to 50 ℃	
_	°F	32 to 122 °F.	
Resolution	°C	0.1 ℃	
	°F	0.1 °F	
Accuracy	°C	±0.8 ℃	
@ 15 to 40 ℃	°F	±1.5 °F	

Black globe temperature (TG)			
Range	°C	0 to 80 ℃	
	°F	32 to 176 °F.	
Resolution	°C	0.1 ℃	
	°F	0.1 °F	
Accuracy	°C	±0.6 ℃	
@ 15 to 40 ℃	°F	±1.1 °F	

Humidity

Humiaity		
Range	5 % to 95 % R.H.	
Resolution	0.1 % R.H.	
Accuracy	≧70% RH :	
	±(3% reading + 1% RH).	
	< 70% RH :	
	±3% RH.	

Dew Point Temp.					
°C		Range	-25.3 ℃ to 48.9 ℃		
		Resolution	0.1 °C		
°F		Range	-13.5 °F to 120.1 °F.		
		Resolution	0.1 °F.		
Remark :	* Dew Point Temp. value is calculated from the				
	Humidity/Air Temp. measurement automatically.				
* The Dew Point Temp. accuracy is sum accuracy value					
	of Humidity & Air Temperature measurement				

Wet bulb Temp

wet buib remp.				
°C		Range	-21.6 ℃ to 50.0 ℃	
		Resolution	0.1 °C	
۴		Range	-6.9 °F to 122.0 °F.	
		Resolution	0.1 °F.	
Remark : * Wet bulb display value is calculated from the				
Humidity/Air Temp. measurement automatically.				
* The Dew Point accuracy is sum accuracy value of				
Humidity & Air temperature measurement				
@ Above specification tests under the environment RF Field Strength				

less than 3 V/M & frequency less than 30 MHz only.



* Appearance and specifications listed in this brochure are subject to change without notice.